
Moore And Wright Bore Gauge 316 Series



Moore And Wright Bore Gauge 316 Series

MEASURING AND READING METHODS



- Measuring in cross section, at position A, the hand of indicator points to the Min. reading, this is the right measuring point, see figure A.
- Turning the bore gage at direction showing at the right figure, finding the position A.





- Measuring in vertical section, at position B, the hand of indicator points to the Min. reading, this is the right measuring point, see figure B.
- Turning the bore gage at direction showing at the right figure, finding the position B.







In order to get the exact data,must measure several positions generally,see the left figure.

SPECIFICATIONS

Measuring Range	Measuring Depth	Anvil	Washer	Component
6-10mm(0.24-0.4in)	40mm(1.57in)	9		
10-18mm(0.4-0.7in)	100mm(4in)	9	1	
18-35mm(0.7-1.5in)	125mm(5in)	7(8)		
18-35mm(0.7-1.5in)	150mm(6in)	9(10)	2	
35-50mm(1.4-2.4in)	150mm(6in)	4(6)	4(3)	
50-100mm(2-4in)	150mm(6in)	11	4(3)	
50-160mm(2-6in)	150mm(6in)	12(11)	4(3)	1
160-250mm(6-10in)	400mm(16in)	5(6)	5	1
250-450mm(10-16in)	400mm(16in)	5(6)	5	2

CAUTION

- Do not disassemble or modify the gage.
- Do not subject the gage to blow or knocks.
- Clean and apply antirust after using, disassemble the indicator (laying indicator with the gage together may effect the precision), place the gage in the box.
- Do not embezzle the anvil, washer etc.