


## Angle finder instruction




Power  
3V Cr2032  
Lithium battery

2000h

High Resolution

0.05°

## INSTRUCTION OF BUTTON AND LCD



## ABS setting



Under "ABS" mode

- (1) automatic record the original ZERO position after power off
- (2) display always reads upright

## APPLICATION OF HIGH QUALITY LEVEL VIAL



## INSTRUCTION OF ANALOGUE QUADRANT FOR MOVING BLADE

